BAAQMD Title V Permit 6 Month Monitoring Report

From 1/1/2017 to 6/30/2017

	A0010 Chevron Richmond Refinery	inery			
	Facility Address: 841 Chevron Way		Mailing Address PO Box 1272		
	City: <u>Richmond</u> State: <u>CA</u> Zip Code: <u>94801-</u>		City: <u>Richmond</u> State: <u>CA</u> Zip Code: <u>94802-0272</u>		
	Contact: Cameron Toy	oy Title: Compliance Technicia	<u>e Technician.</u> Phone: <u>(510) 242-4449</u>		
Inoperable monitors as defined by BAAQMD Regulations 1-522 and 1-523 for the reporting period are summarized below:	522 and 1-523 for the reporting period are summa	rrized below:			
Started Stopped	Source (S#) Abatement Emission Device (A#) Point (P#)	Fuel CEM GLM Gas Parametri NOx SO2	Opacity/ NOx SO2 CO H2S TRS NH3 O2 CO2 H2O LTA Lead Steam Flow Wind Dir, Speed pH Temp, VOC. Press.	ind eed pH Temp.	Gauge VOC. Press.
2/10/2017 3:45 AM 2/11/2017 4:38 PM 🖸 Discovered On: 2/13/2017	\$4171				
Event Description: The F-355 361 East NOX, CO, O2 analyzers be	The F-355 361 East NOX, CO, O2 analyzers became inoperative on 2/10/17 at 0345 hours. The analyzers were repaired and returned to service on 2/	s were repaired and returned to	service on 2/11/17 at 1638 hours.		
2/10/2017 3:45 AM 2/13/2017 3:18 PM	\$4171 .				
the transfer to the transfer t	The state of the s	alyzors were repaired and put of	CRITICO SELVICE OH 2/11/1/ At 15/10 HOULS.		
2/10/2017 3:45 AM 2/11/2017 3:22 PM Discovered On: 2/13/2017 Event Description: The F-355 361 West NOX, CO, O2 analyzers became inoperative on 2/10/17 at 0345 hours. The analyzers were repaired and returned to service on 2/11/17 at 1522 hours.	\$4171 came inoperative on 2/10/17 at 0345 hours. The analyzer	rs were repaired and returned to	SET □ SE □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □		
3:18 PM	S4171			7	-
2/13/201/ 2017 ne F-355 360 Eas	became inoperative on 2/10/17 at 0345 hours. The analy	yzers were repaired and put bac	k into service on 2/11/17 at 1518 hours.		
2/13/2017 12:52 PM 2/14/2017 3:31 PM Siscovered On: 2/14/2017	S4171				
Event Description: F355, 360W Nox, Co, 02 Analyzers became inoperative on 2/13/17 at 12:52 hours. The analyzers were repaired and returned to service on 2/14/17 at	perative on 2/13/17 at 12:52 hours. The analyzers were re	repaired and returned to service	on 2/14/17 at 15:31 hours .		
2/17/2017 11:00 PM 2/21/2017 2:50 PM G Discovered On: 2/20/2017 Event Description: UPDATE (RCA# 07C34); Repairs complete; the	M 2/21/2017 2:50 PM S 4285 W 2/2017 UPDATE (RCA# 07C34): Repairs complete: the V-65 O2 analyzer was calibrated and returned to service on 2/21/17 at 1450 hours.	e on 2/21/17 at 1450 hours			
	7/17 at 2200 hours: renairs are annoing				

Certification Statement

I certify under penalty of law that based on the information and belief formed after reasonable-inquiry, the statements and information in this document and in all attachments and office/majorials are true, accurate, and complete.

Signature of Responsible Official

Print Name Kory Judd

General Manager Richmond Refinery 26 July 2017

Fuel Opacity/ Opacity/ Wind Gauge CEM GLM Gas Parametri NOx SO2 CO H2S TRS NH3 O2 CO2 H2O LTA Lead Steam Flow Wind Dir. Speed pH Temp. VOC. Press.